03500.015462 PATENT

#### IN THE UNITED STATES PATENT AND TRADEMARK OFFICE.

In re Application of:

Kiyotaka Wasa, et al.

Application No.: 09/880,757

Filed: June 15, 2001

For: PROCESS OF MANUFACTURING A PIEZOELECTRIC ELEMENT

PROCESS OF MANUFACTURING A PIEZOELECTRIC ELEMENT

November 7, 2007

Commissioner for Patents

P.O. Box 1450

Alexandria, Virginia 22313-1450

ATTENTION: CERTIFICATE OF CORRECTION BRANCH

## REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The fee for this Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Daniel S. Glueck/ Daniel S. Glueck Attorney for Patentees Registration No. 37,838

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800 Facsimile: (212) 218-2200

DSG/mcm

# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,120,978 B2

DATED: October 17, 2006

INVENTOR(S) : Kiyotaka Wasa, et al. Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 3

Line 18, "is" should read --be--.

## COLUMN 4

Line 67, "o" should read --to--.

# COLUMN 5

Line 26, "side" should read --sides--.

# COLUMN 6

Line 28, "porion" should read --portion--.

# COLUMN 7

Line 52, "think" should read --thin--.

#### COLUMN 8

Line 3, "chamber 3," should read --chambers 3,--.

Line 16, "correspond" should read --corresponding--.

Line 34, "martial" should read --material--.

Line 42, "from" should read --form--.

Line 57, "think" should read --thin--.

# MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DSG/mcm PATENT NO. 7,120,978 B2

No. of add'l. copies @ 30¢ per page



# UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7.120,978 B2

**DATED** : October 17, 2006

INVENTOR(S): Kiyotaka Wasa, et al. Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

# COLUMN 13

Line 38, "thickness" should read --thicknesses--.

## COLUMN 18

Line 1, "from" should read --form--.

Line 6, "puttering." should read --sputtering. --.

## COLUMN 19

Line 20, "from" should read --form--.

#### MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800

(212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30) DSG/mcm PATENT NO. 7,120,978 B2

No. of add'l. copies @ 30¢ per page

